



Timestamp	Function title	Module	Function label	For which production year this function have worked ?	Short description
4/2/2011 8:49:54	LED Tail Light Upgrade for E92	NFRM	see description, multiple labels	2010	KALTUE_BL_M2_43_M2_9 aktiv KALTUE_BFD_M1_5_M1_37 aktiv WARMUE_BFD_M1_5_M1_37 aktiv WARMUE_BL_M2_43_M2_9 aktiv
6/24/2011 1:51:57	Cruise Control Speed Set	KOMBI	TEMPOMAT_SETZ_ANZ_DAUER	2006, 2007, 2008	set all these to nicht_aktiv and this works for a 2010 E92 M3 with the FRM3 footwell module. no more brake light error messages.
6/29/2011 12:27:	46 Doubleimpul_Warnt	NFRM	Euro Hazard lights	2007, 2008	TEMPOMAT_SETZ_ANZ_DAUER set it to wert_02 and the speed will be on dispay for fe secconds.
7/11/2011 10:24:	Disable Keyhole 37 Alarm	CAS	SCHAERFEN/ENTSCHAERFEN	2011	Makes the hazard light double flash instead of single flash Set the key in the door to not disarm the alarm system, only remote will disarm alarm system. Change schloss_und_fernbedienung -> nur_mit_fernbedienung
7/12/2011 5:22:16	Disable Seat Belt Reminder in iDrive	ABG	CC_GURTWARNUNG_1	2011	Disable Seat Belt Reminder in iDrive. change from aktiv to nicht_aktiv (Note: Some cars may need this to be disabled to get rid of the seat belt chime)
12/6/2011 10:40:	13 DRL	KOMBI	Light	2006	fwe
2/12/2012 4:09:31	Cruise Control, change units from miles to kilometers	CAS	C0C_V_EINHEIT	2008	Module DSC!!! wert_00 --> km/h, wert_01 --> mls C0C_SETZ_V_MAX wert_01 --> km/h (30-180km/h), wert_02 --> mls (20-110mls)
3/10/2012 10:31:	Weather Radio 25 Band	CAPPL (CCC)	WEATHERBAND	2008	Adds NOAA Weather Radio band. Change to "aktiv" Works in Canada too ( <a href="http://en.wikipedia.org/wiki/Weatherradio_Canada">http://en.wikipedia.org/wiki/Weatherradio_Canada</a> )
7/17/2012 16:19:	mirrors 21 electrochrome	FRM	spiegel_elektrochrome	2007	aktiv if retrofit with electrochrome mirrors
9/2/2012 23:04:23	Fog Light Delete	FRM	KALTCHECK_E89_FL_E7X_NSW	2008	Set to nicht_aktiv. Also, you must set the following to nicht_aktiv as well: KALTCHECK_E89_NSW_E7X_FL . To disable the fog light button switch and the warm testing, set the following two functions to nicht_aktiv: WARMCHECK_E89_FL_E7X_NSW and WARMCHECK_E89_NSW_E7X_FL
3/18/2013 14:13:	56 Angel Eyes Error	NFRM	KALTCHECK_RL_BL_1_ALS_TFL	2008	Disables cold check of angel eyes (need to code both cold and warm check)
3/18/2013 14:15:	04 Angel Eyes Error	NFRM	WARMCHECK_RL_BL_1_ALS_TFI	2008	Disables warm check of angel eyes (need to code both cold and warm check)
7/4/2013 10:43:13	DUAL_SP_NSW_LMA		nicht_aktiv	2008	Disables Dual Voltage (PWM) for E60 HID FOG Lights.
7/4/2013 10:43:34	DUAL_SP_NSW_LMA		nicht_aktiv	2008	Disables Dual Voltage (PWM) for E60 HID FOG Lights.